





W CNC BUTT FUSION WELDING MACHINE

Model: AUTO315

Application Area:

HIGHLY Innovative CNC Controlled Fully Automatic Butt Fusion Welding Machine equipped with auto ejecting heating plate used for welding of PE, PP, PB & PVDF pipes & fittings for all pressure & SDR stages suitable for OD up to 315 MM. On-site printing of the welding report possible with in-built printer in addition to the standard usb report makes the operation more comfortable and easy



Technical Data:

Name : CNC BUTT FUSION WELDING MACHINE

Item code : AUTO315 : 160-315 MM Welding Range

Clamping Inserts : 160, 180, 200, 225, 250, 280 & main clamp 315 MM

Voltage : ~220V, 50/ 60Hz

Heater Power : 3.7 KW Facer Power : 1.2 KW Hydraulic Unit Power : 0.75 KW Total power requirements : 5.65 KW

: 2000 Welding Reports. Data Recording Capacity

Machine Weight : 280 Kgs





SAMPLE OF WELDING REPORT BY DATALOGGER

Date/Time:	2009-10-15	14:08
Machine:		
Machine NO.:	O90214083	
Commission:	SAAA003-B040-CC012-DD	
	2500-EE4006	
Joint NO.:	GJ48-086	
Welder:	A00015	
Weather:	cloudy	
Safeguard:	Yes	
Ambient Temp. (°C):	12	
Material:	PE100	
Diameter(mm):	200	
Wall thickness(mm):	22.3	
SDR:	9	
Drag Pres.(bar):	5.0	
	NOM.	ACT
Heating temp(°C):	220	221
Heating Pr.(bar):	9.8	9.9
B. Build. T .(S):		108
Soak. Pres. (bar):	1.0	1.0
Soak. Time (S):	223	223
Change Time (S):	10.5	8.5
P. Build. Time (S):	13	10
Join. Pres. (bar):	9.8	10.0
Cooling Time(S):	2040	2040
9(0).		
	Machine NO.: Commission: Joint NO.: Welder: Weather: Safeguard: Ambient Temp. (°C): Material: Diameter(mm): Wall thickness(mm): SDR: Drag Pres.(bar): Heating temp(°C): Heating Pr.(bar): B. Build. T.(S): Soak. Pres. (bar): Soak. Time (S): Change Time (S): P. Build. Time (S): Join. Pres. (bar):	Machine: AUTO315 Machine NO.: O90214083 Commission: SAAA003-B040-CC 2500-EE4006 Joint NO.: GJ48-086 Welder: A00015 Weather: cloudy Safeguard: Yes Ambient Temp. 12 (°C): PE100 Diameter(mm): 200 Wall thickness(mm): 22.3 SDR: 9 Drag Pres.(bar): 5.0 NOM. Heating temp(°C): 220 Heating temp(°C): 9.8 B. Build. T.(S): — Soak. Pres. (bar): 1.0 Soak. Time (S): 223 Change Time (S): 10.5 P. Build. Time (S): 13 Join. Pres. (bar): 9.8

